



ISD #381

Lake Superior Schools

William Kelley Addition and Renovation

ICS Weekly Progress Report

Friday – October 04, 2024

Address: 137 Banks Blvd. Silver Bay, Minnesota 55614

William Kelley Addition and Renovation



Completed week ending October 04, 2024

-  Flooring in music rooms and art room
-  Install wall coverings and acoustical wall panels
-  Continue corridor wall tile
-  Ceiling grid in corridors
-  Continue casework installation
-  Continue doors and hardware installation
-  Polished corridor terrazzo flooring
-  Installed visual display boards/markerboards
-  Finished installation of bathroom fixtures
-  Touch up painting
-  Punch list
-  Commissioning, testing and balancing of mechanical systems



Upcoming planned work for Music/Art Rooms

-  Exterior sheet metal roof coping
-  District to wax music and art room floors
-  Finish installation of wall coverings and acoustical wall panels
-  Finish corridor wall tile
-  Finish casework installation
-  Finish doors and hardware installation
-  Light fixtures and HVAC diffusers in main corridor
-  Ceiling pad in main corridor
-  Punch list
-  Commissioning, testing and balancing of mechanical systems



ISD #381

Lake Superior Schools

William Kelley Addition and Renovation

ICS Weekly Progress Report

Friday – October 04, 2024

Address: 137 Banks Blvd. Silver Bay, Minnesota 55614

Progress Photos



Ceilings, acoustical panels, markerboards, flooring, doors and fin tube covers complete in Music Rooms



ISD #381

Lake Superior Schools

William Kelley Addition and Renovation

ICS Weekly Progress Report

Friday – October 04, 2024

Address: 137 Banks Blvd. Silver Bay, Minnesota 55614



Main corridor, painting, wall tile, flooring and soffits



Lower level, corridor/elevator lobby wall tile, flooring and ceiling completed



ISD #381

Lake Superior Schools

William Kelley Addition and Renovation

ICS Weekly Progress Report

Friday – October 04, 2024

Address: 137 Banks Blvd. Silver Bay, Minnesota 55614



Art Room casework installed and floor preparation for concrete sealing



Common area wall tile and lavatory sink